

Code Revision: **1.2**

Release Date: **03/23/2012**

Validated FW Image: **C.3.N**

Notes:

This is the update version for FieldUpdater Release for the SF-2000 product family.

New Features:

- None

Bug Fixes:

- Fixed an issue with FieldUpdater 1.1 that sometimes can't complete the firmware update with Intel RST driver v10.7 installed. (Intel RST driver v10.8 is also required for this fix.)

Known Issues:

- If your platform is an AMD chipset, FieldUpdater 1.2 may not work.

Notes:

- FieldUpdater is not compatible with the SF-1000 product family.
- Supported on Windows/2000/XP/Vista/Win7 and Fedora Core 12 64-bit and Fedora Core 14 32-bit.
- Must generate .FFP and individual .VIC files from Genesis Utilities Version 1.4.8 and later.
- The OEM partner must choose to replace the SandForce logo with an image of their own. For details, please refer to the FieldUpdater User Manual revision 1.1.